Printed on: 8/23/2010 8:18:21 AM

National Transportation Safety Board	1	NTSB ID:	DCA10RA06	69	Aircraft Registration Number: N847HK				
FACTUAL REPORT		Occurrence	ce Date: 06/16	6/2010	Most Critical Injury: Minor				
AVIATION	(	Occurrenc	ce Type: Accid	lent	Investigated By: Foreign				
Location/Time									
Nearest City/Place	State Z		o Code	Local Time	Time Zone				
Ottawa			1430		EDT	EDT			
Airport Proximity: Distance			ee From Landing Facility:						
Aircraft Information Summary									
Aircraft Manufacturer			Model/Series	5			Type of Aircraft		
EMBRAER		EMB-145L	R			Airplane			
Revenue Sightseeing Flight: No	Air Medical Transport Flight: No								

## Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On June 16, 2010, at approximately 2:30 pm local time, an Embraer EMB145 airplane, N847HK, equipped with Rolls Royce AE3007A engines and operated by Trans States Airlines as flight 8050 (dba United Express), overran runway 07 at Ottawa International Airport, Ottawa, Canada during landing. The airplane originated from Washington Dulles International Airport (IAD). Multiple injuries were reported of the 33 passengers and 3 crewmembers on board the flight.

The investigation is being conducted by the Transportation Safety Board (TSB) of Canada. The NTSB has designated a U.S. Accredited Representative as the State of the Operator, the engines, and various subsystems on the EMB145.

All inquiries on this investigation should be directed to:

Transportation Safety Board of Canada 200 Promenade du Portage Place du Centre 4th Floor Gatineau, Quebec K1A 1K8 (819) 994-3741 http://www.tsb.gc.ca/eng/airops@bst-tsb.gc.ca
Updated on Jul 23 2010 10:24PM

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DCA10RA069

Occurrence Date: 06/16/2010

AVIATION	Occurre	ence Type:	: Ac	cident								
Landing Facility/Approach Int	formation			_								
Airport Name	rport ID:	Aiı	irport Elevation Ft. MSL				unway Length		Runwa	ay Width		
Runway Surface Type:												
Runway Surface Condition:									_	_		
Approach/Arrival Flown:												
VFR Approach/Landing:												
Aircraft Information												
Aircraft Manufacturer EMBRAER			Model/ EMB-							l Number 00857		
Airworthiness Certificate(s):												
Landing Gear Type:		-										
Amateur Built Acft? No	Certified Max Gross Wt.						Numbe	r of Eng	gines:	2		
Engine Type: Turbo Fan			Engine Manufacturer: Model/Series: ROLLS-ROYC AE3007 SER						Rated Power: 7200 HP			
- Aircraft Inspection Information												
Type of Last Inspection		Da	Date of Last Inspection Time Since				nce Last Insp	nce Last Inspection  Hours				al Time Hours
- Emergency Locator Transmitter (I	ELT) Information								•			
ELT Installed?/Type		E'	LT Operat	ted?	,	ELT Aic	ded in Locatin	g Accide	ent Site?	>		
Owner/Operator Information												
Registered Aircraft Owner	Street Address 11495 NAVAID RD											
TRANS STATES AIRLINES LI	LC		City BRIDGETON							State MO		Zip Code 63044-2335
Or and Almoret			Street A	ddre	ess						•	
Operator of Aircraft TRANS STATES AIRLINES IN	City						State	• [	Zip Code			
Operator Does Business As:		Operator Designator Code: RAIA										
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s):	: Flag Carrier/Dom	nestic										
Operating Certificate:				$\top$	Operator Certific	cate:						
Regulation Flight Conducted Under	r: Part 121: Air Ca	arrier										
Type of Flight Operation Conducted	d: Scheduled; Inte	rnational	; Passen	 iger	Only							
	J	FACTUA	L REPO	RT	- AVIATION							Page 2

## National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: DCA10RA069

Occurrence Date: 06/16/2010

AVIATION				Occurrence Type: Accident													
First Pilot Information																	
Name City								ity	/			Sta	ate	Date	e of Birth	Age	
Sex: Seat Occupied: Occupational Pilot?											Certificate Number:						
Certificate(s):																	
Airplane Rating(s):																	
Rotorcraft/Glider/LTA:																	
Instrument	Rating(s):																
Instructor Rating(s):																	
Current Bie	ennial Flight Revie	∍w?															
Medical Ce	ert.:	Medica	al Cert. St	atus	;:						Date of Last Medical Exam:						
- Flight Tim			This Make and Model	$\Box$	Airplane Airplane Single Engine Mult-Engine			Night	Actua	Instrument Simulate			Rotorcraft		Glider	Lighter Than Air	
Total Time				$\Box$													
Pilot In Cor	mmand(PIC)			$\dashv$			$\perp$		<u> </u>			$\perp$					
Instructor			<u> </u>	$\dashv$			$\perp$		<u> </u>			_					
Instruction	Received			$\dashv$			丄							ightharpoonup			
Last 90 Da	ys		<u> </u>	4		<u> </u>	4		<u> </u>			4		$\dashv$			
Last 30 Day	ys		<u> </u>	4		<b></b>	4		<u> </u>					$\dashv$			
Last 24 Ho	urs		<u> </u>	丄			丄		<u> </u>					丄			
Seatbelt Us	sed?	Shou	ulder Harn	ess I	Used?			Toxico	ology P	erform	erformed? Second Pilot? Yes						
Flight Plan/Itinerary																	
Type of Flig	ght Plan Filed:																
Departure F	Point							State	,	Airpo	ort Identifier Departure Time 1				Time Zone		
Destination	1							State	0								
Desunation								State		Alipo	rport Identifier						
Type of Cle	earance:																
Type of Air	space:																
Weather	Information																
Source of	Wx Information:																
	<u> </u>				FACTUAL	REPORT	 ' _ А	AVIATIO								Page 3	

## National Transportation Safety Board FACTUAL REPORT

NTSB ID: DCA10RA069

Occurrence Date: 06/16/2010

	Occurrent	e Type:	: Acciden	t							
Weather	AVIATION Information						•				
WOF ID	Observation Time	Time Zone	one WOF Elevation WOF Distance From Acc						Direction From Accident Site		
			_								
			Ft.	. MSL			NM		Deg. Mag.		
Sky/Lowes	st Cloud Condition:					Ft. AGL	. Condition of	of Ligh	nt:		
Lowest Ce	iling:		Ft.	AGL	Visibi	lity:	SM	Altir	meter: "Hg		
Temperatu	ıre: °C	Dew Point:	Weat	Weather Conditions at Accident Site:							
Wind Direc	ction:	Wind Speed	d: :t		Wind	d Gusts:					
Visibility (R	RVR): Ft.	Visibility (R'	VV)	SM							
Precip and	d/or Obscuration:										
Assident	Information										
			<del></del>				T				
Aircraft Dar	mage: Substantial		Aircraft Fire	e: None	<del></del>		Aircraft Exp	olosio	n None		
- Injury Sur	mmary Matrix	Fatal Se	erious Mino	r	None	TOTAL					
First Pil	lot			1		1					
Second	d Pilot			1		1					
Studen	t Pilot										
Flight In	nstructor										
Check I	Pilot										
Flight E	Engineer				1	1					
Cabin <i>F</i>	Cabin Attendants										
Other C	Crew										
Passen	ngers			1	32	33					
- TOTAL A	ABOARD -			3	33	36					
Other G	Ground Ground										
- GRANE	O TOTAL -			3	33 36						

National Transportation Safety Board

NTSB ID: DCA10RA069

National Transportation Safety Doard		
FACTUAL REPORT	Occurrence Date: 06/16/2010	
AVIATION	Occurrence Type: Accident	
Administrative Information	7. 1.00.00	
Investigator-In-Charge (IIC)		
John W. Lovell		
Additional Persons Participating in This Accident	/Incident Investigation:	